

# Oil Field Environmental Incident Summary

**Incident:** 20141231123951 **Date/Time of Notice:** 12/31/2014 12:39

**Responsible Party:** Anytime Hydroexcavation

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** JERSEY 29-6XH

**Field Name:** ALKALI CREEK

**Well File #:** 28333

**Date Incident:** 12/31/2014 **Time Incident:** 09:00

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 153

**Rng:** 93

**Sec:** 6

**Qtr:**

**Location Description:**

**Submitted By:** Patrick Skillestad

**Received By:**

**Contact Person:** Daniel Crowe  
#7 3rd Street SE  
Suite 101  
Minot, ND 58701

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	2	Barrels	2	Barrels		

**Description of Other Released Contaminant:**

Recycle Water

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

20 ft x 20 ft, 1 ft x 15 ft, 1 ft x 20 ft

**Potential Environmental Impacts:**

Location soil

**Action Taken or Planned:**

Hatch was secured on pit tank, fluid and contaminated materials were removed and put into pit tank.

**Wastes Disposal Location:** Pit tank on location.

**Agencies Involved:**

**Updates**

**Date:** 12/31/2014 **Status:** Reviewed - Assigned to Other Agency

**Author:** Washek, Sandi

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:** 2.00 barrels

**Updated Other Contaminant** Recycled water

**Notes:**

Product remained on site of pad. O&G is lead.